


HEAD WOUND DRESSING



01.

Place pad on wound and wrap the elastic bandage wrapping leader around head.



04.

Cupping the chin for comfort and stability, continue to wrap the elastic bandage.



02.

Insert elastic bandage into pressure applicator and wrap around head. Pull back, forcing pressure applicator down onto pad.



05.

Secure hooking ends of closure bar into elastic bandage.



03.

Hook the wrapping leader behind a corner of the pressure applicator to turn the direction of bandaging.